

MATERIAL SAFETY DATA SHEETS (MSDS) On-Line OSHA-Required Health And Safety Information!

Section 1

MATERIAL SAFETY DATA SHEET # 50 Hercules PVC Heavy Duty Cement

Date Prepared: 01-Feb-90

Last Reviewed: 01-Jul-98

Hercules Chemical Co, Inc. 111 South Street Passaic, NJ 07055-7398 Tel (800) 221-9330 Fax (800) 333-3456 E-Mail info@herchem.com

Meets OSHA 29 CFR 1910.1200

Section 2 - Hazardous Ingredients/Identity Information

Hazardous Components (Specific Chemical Identity; Comman Name(s), CAS Numbers)	OSHA PEL	ACGIH TLV	Other Limits	% Upper Bound Limits if SARA Reportable
Tetrahydrofuran (109-99-9)	200PPM	200PPM	N/A	
Methyl Ethyl Ketone (78-93-3)	200PPM	200PPM	N/A	5%
Cyclohexanone (108-94-1)	25PPM	25PPM	N/A	144- 644

HMIS Hazard Rating: Health: 3 Flammability: 4 Reactivity: 1 Personal Protection: G

Section 3 - Physical/Chemical Characteristics

Boiling Point (°F):	Specific Gravity (H ₂ 0=1):	Vapor Density (Air=1):	Vapor Pressure (mm Hg):
151 Based on first boiling component-THF	0.935 ± 0.03	2.0 to 2.5	143 Based on first boiling component-THF
Melting Point (°F):	Evaporation Rate (Butyl Acetate=1):	Solubility in Water:	
N/A	7-11	60% to 85%	•
Appearance And Color: Clear Viso	ous Liquid	Odor: Ethereal &	Acetone-like

Section 4 - Fire And Explosion Hazard Data

Flash Point: Flammable Limits: LEL: UEL: 6.0 °F. (TCC) (Based on THF) 2% 11.8%

Extinguishing Media: Foam/Dry Chemical/Carbon Dioxide

Special Firefighting Procedures:

Handle as flammable liquid. Wear SCBA (Self-Contained Breathing Apparatus) & chemical goggles. Water may be ineffective, but should be used to keep fire exposed containers cool.

Unusual Fire And Explosion Hazards:

Vapor is heavier than air and travels considerable distance to source of ignition and flashback. On long standing may form peroxides which may cause violent reaction especially upon evaporation to dryness.

Section 5 - Reactivity Data

Stability: Stable Conditions To Avoid: Keep in closed containers away from sparks and open flame.

Incompatability Strong oxidizing materials, Lithium Aluminum Hydride, Sodium Aluminum

(Materials To Avoid): Hydroxide & Sodium & Potassium Hydroxides.

Hazardous Carbon dioxide and carbon monoxide are formed. Irritating Peroxide fumes

Decomposition: formed when heated to decomposition.

Hazardous
Polymerizatrion:

Avoid excessive exposure to air and cationic initiators like Lewis Acids.

Section 6 - Health Hazard Data

Routes of Entry: Inhalation? YES/Primary Skin? YES/Primary Ingestion? YES/Secondary

Health Hazards:

Corrosive to eyes and skin irritant. Severe overexposure can cause headache, dizziness & narcosis. May cause Dermatosis and Dermatitis with prolonged repeated contact.

Carcinogenicity: NTP? NO IARC? NO OSHA Regulated? NO

Signs And Symptoms of Exposure:

INGESTION: No effects of exposure expected. INHALATION: Will cause irritation of mucous membranes, nose, eyes, and throat, coughing, difficulty of breathing. Exposure to high vapor concentration may cause headache, dizziness, nausea and narcosis. SKIN CONTACT: Prolonged contact causes common solvent defatting effect. EYE CONTACT: Vapors slightly uncomfortable, splashes irritating. Will cause painful burning or stinging of eyes and lids and watering of the eyes and inflammation of conjunctiva.

Medical Conditions Generally Aggravated By Exposure:

No data found

Emergency And First Aid Procedures:

INGESTION: Do not induce vomiting. If conscious, dilute by giving two glasses of water. Call a physician immediately. INHALATION: Remove to fresh air, if not breathing; give artificial respiration preferably mouth to mouth. If breathing is difficult give oxygen. Call a physician. SKIN CONTACT: Wash affected skin area with soapy water. Remove contaminated clothing. EYE CONTACT: Immediately flush eyes with plenty of water for 15 minutes. Consult a physician.

Section 7 - Precautions For Safe Handling And Use:

Steps To Be Taken In Case Material Is Released Or Spilled:

Eliminate sources of ignition. Absorb with sand or inert absorbing material and dispose of with solid waste according to federal, state and local regulations. Flush spill area with water, avoid flushing into confined areas.

Waste Disposal Method:

Incinerate in accordance with the federal, state and local regulations.

Precautions To Be Taken In Handling And Storing:

Store in cool well-ventilated area. Keep away from open flame and sources of ignition.

Other Precautions:

Use normal good personal hygiene

Section 8 - Control Measures:

Respiratory Protection:

In confined spaces or other circumstances where adequate ventilation cannot be assured use NIOSH-approved respirator, positive pressure airline mask, or self

contained breathing apparatus.

Ventilation:

Local

As required

Exhaust: Mechanical:

All ventilating devices

must be located so they do not provide a source

of ignition.

Special: When using cements in an area of

Other: limited ventilation, use a ventilation device such as a fan or air mover to maintain a safe air concentration.

N/A

Gloves:

PVA gloves

Eye Protection:

Chemical safety goggles.

Other Protective

Clothing:

*Apron, boots, eye bath, safety shower.

Work/Hygienic Practices:

Wash throughly after handling. Avoid ingestion of the cements. Do not eat or drink

when using cements or in the vicinity where such cements are being used.

| Home Page |

| MSDS | Wholesaler Info | Contractor Info | Homeowner & Industrial Info |

Hercules Chemical Co, Inc. 111 South Street Passaic, NJ 07055-7398 Tel 1-800-221-9330 Fax 1-973-777-4115 E-Mail info@herchem.com For more info send <u>E-Mail</u> to info@herchem.com ©Hercules Chemical Comp., Inc. All Rights Reserved.